


TAIN WILL NOT FUNCTION

IF UNIT IS NOT ABSOLUTELY LEVEL FOUN-



2,

TF-42 TELESCOPING FOUNTAIN


IMPORTANT

ABSOLUTE PERPENDICULAR ALIGNMENT IS NECESSARY FOR PROPER OPERATION OF UNIT.

LEVEL HOUSING WITH AID OF CARPENTER'S SQUARE AND SPIRIT LEVEL.

_

fountains for pools



(818) 886-7674 • Fax (818) 886-4658

NOTE:
DIMENSIONS APPLY TO
MODEL TF-42 ONLY.